

Work Order (Bid Form)

Auditor: Scott Haislip (615) 274-2565 or (615) 424-2565

WORK ORDER INFORMATION

Work Order Name: WO/10010MC1941/1

Work Order Type: Weatherization

Audit Name: 10010MC1941

CLI	EN	T IN	FO	RM	AT	ION

Client Name: Address:

Client ID: 10010MC1941 SPRINGFIELD, TN 37172

Alt. Client ID:

AGENCY INFORMATION

Agency: Mid-Cumberland Community Action Agency Agency Phone: (615) 742-1113

Fax:

Address: P.O.Box 310, 233 Legend Drive, Suite 103

Lebanon, TN 37088-0310 Email Address:

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

SITE BUILT 1963 LEAD PAINT LIKELY, MASONITE SIDING 852 SQ FT 8 WINDOWS 2 DOORS

Client Name: Client ID: 10010MC1941 Alt. Client ID: Work Order (Bid Form)
Work Order Name: WO/10010MC1941/1

Report Run On: 5/16/2010

DOE Weatherization Assistant Version 8.6.0 Page 1 of 13

Measures

Measure 1 USE	LEAD PAINT SAFETY	PRACTICI	ES	Componen	ts		ı	Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety	OTHER	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 2 INST	ALL 2 SMOKE ALARM	S		Componen				Inspected
Comment			Ofv	Estimated		Otv	Actual	
Comment # Material / Labor	Description / Comment	Units Each	Qty 2	-		Qty		Inspected Total
Comment # Material / Labor Health and Safety	Description / Comment	Units	-	Estimated		Qty	Actual	
Comment # Material / Labor	Description / Comment	Units	-	Estimated		Qty	Actual	
Comment # Material / Labor Health and Safety	Description / Comment	Units	-	Estimated		Qty	Actual	
Comment # Material / Labor Health and Safety	Description / Comment	Units Each	2	Estimated Unit Cost			Actual	
# Material / Labor Health and Safety Other Detail	Description / Comment	Units Each	2	Estimated			Actual Unit Cost	
Comment # Material / Labor Health and Safety	Description / Comment	Units Each	2	Estimated Unit Cost			Actual Unit Cost	
# Material / Labor Health and Safety Other Detail	Description / Comment	Units Each	2	Estimated Unit Cost			Actual Unit Cost	

measure 5 insi	ALL 6 MIL VAPOR BAR	RIER		Componen	ts		ı	Inspected
Comment 895 SQ	FT; CONTRACTOR TO '	VERIFY						
				Estimated	<u>'</u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety	6 MIL VAPOR BARRIER	Each	1					
Other Detail								
			Measur	e Sub Total:] .	Sub Total:	
	ALL EXHAUST VENT H VE IN KITCHEN (NONE			Componen	ts		1	Inspected
STO				•			1	Inspected
STO				Componen Estimated			Actual	Inspected
STO' Comment				•		Qty		Inspected Total
STO' Comment	VE IN KITCHEN (NONE Description / Comment	PRESEN	T)	Estimated	<u>, </u>	Qty	Actual	
STO ¹ Comment # Material / Labor	VE IN KITCHEN (NONE Description / Comment	PRESEN Units	T) Qty	Estimated	<u>, </u>	Qty	Actual	
STO Comment # Material / Labor Health and Safety	VE IN KITCHEN (NONE Description / Comment	PRESEN Units	T) Qty	Estimated	<u>, </u>	Qty	Actual	
STO Comment # Material / Labor Health and Safety	VE IN KITCHEN (NONE Description / Comment	PRESEN Units	T) Qty	Estimated	<u>, </u>	Qty	Actual	
STO Comment # Material / Labor Health and Safety	VE IN KITCHEN (NONE Description / Comment	PRESEN Units	Qty 1	Estimated	<u>, </u>		Actual	
STO Comment # Material / Labor Health and Safety Other Detail	VE IN KITCHEN (NONE Description / Comment	PRESEN Units	Qty 1	Estimated Unit Cost	<u>, </u>		Actual Unit Cost	
STO Comment # Material / Labor Health and Safety	VE IN KITCHEN (NONE Description / Comment	PRESEN Units	Qty 1	Estimated Unit Cost	<u>, </u>		Actual Unit Cost	
STO Comment # Material / Labor Health and Safety Other Detail	VE IN KITCHEN (NONE Description / Comment	PRESEN Units	Qty 1	Estimated Unit Cost	<u>, </u>		Actual Unit Cost	

WITI	END DRYER VENT TO I H METAL PIPE & RAIN(ITING IN CRAWL)		Κ	Componen	ts		1	mspeciel
Comment	,			Fatherster			A = (I	
4 Matarial / Labor	December 10 manager	Unito		Estimated			Actual	Total
# Material / Labor	Description / Comment	Units 	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety	OTHER	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
	TALL POP OFF VALVE INET STYLE WATER H			Componen				Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety	POP OFF VALVE DRAIN	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

	SEAL PLUMBING PENETRA JNDER KITCHEN SINK	ATIONS		Componen	its		1	Inspected
Comment				Estimated	1		Actual	
# Material / Labo	r Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1					
Other Detail						1		
] []		
			Measur	e Sub Total:] []	Sub Total:	
Field Notes:								
	JNDER BATHROOM VANIT COMMODE SUPPLY LINE	Y &		Estimated	,		Actual	
# Material / Labo	r Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1]		
Other Detail								
			Measur	e Sub Total:]	Sub Total:	
Field Notes:								

	ATHER STRIP FRONT & ORS	BACK		Componen	its			Inspected
Comment				-				
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Doors	WEATHER STRIP	Each	1					
Other Detail						7		
			Measur	e Sub Total:] ;	Sub Total:	
DO	D DOOR SWEEP TO FRO	ONT & BA	СК	Componen			Actual	Inspected
DO Comment		ONT & BA	.CK	•		Qty		Inspected
DO Comment	ORS			Estimated	<u> </u>	Qty	Actual	
DO Comment # Material / Labor	ORS Description / Comment	Units	Qty	Estimated	<u> </u>	Qty	Actual	
DO Comment # Material / Labor Doors	ORS Description / Comment	Units	Qty	Estimated	<u> </u>	Qty	Actual	
DO Comment # Material / Labor Doors	ORS Description / Comment	Units	Qty	Estimated	<u> </u>	Qty	Actual	
DO Comment # Material / Labor Doors	ORS Description / Comment	Units Each	Qty 1	Estimated	<u> </u>		Actual	

	AL AROUND WINDOW A ING ROOM	C UNIT IN	I	Componen	ts			Inspected
Comment				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
SIN	CHEN BEHIND WATER I IK AREA DXIMATELY 4" HIGH, 8' L			BOARD PR	ESENT			
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

	AL AROUND DRYER VEIOM INTERIOR	NT HOSE		Componen	ts		1	Inspected
Comment					_			
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1					
Other Detail						1		
		1	Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 14 SE	AL ALONG TUB & FLOO	PR IN		Componen				Inspected
Measure 14 SE BA Comment	THROOM		Qfv	Estimated	<u> </u>	Ofv	Actual	
Measure 14 SE BA Comment	ATHROOM Description / Comment	PR IN Units Each	Qty			Qty		Inspected Total
Measure 14 SE BA Comment # Material / Labor Other	THROOM	Units	_	Estimated	<u> </u>	Qty	Actual	
Measure 14 SE BA Comment # Material / Labor	ATHROOM Description / Comment	Units	_	Estimated	<u> </u>	Qty	Actual	
Measure 14 SE BA Comment # Material / Labor Other	ATHROOM Description / Comment	Units	_	Estimated	<u> </u>	Qty	Actual	
Measure 14 SE BA Comment # Material / Labor Other	ATHROOM Description / Comment	Units Each	1	Estimated	<u> </u>		Actual	

Comment		MINDO	W	Componen	ts		ı	nspecte
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1					
Other Detail						_		
			Measur	e Sub Total:			Sub Total:	
	DOW, NEXT TO AC UNI N IT RAINS	T, LEAKS	6					
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	

	AL CRACK IN CORNER (DROOM CLOSET, FRON		JSE	Componen	ts		ı	Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1					
Other Detail						1		
			Measur	e Sub Total:			Sub Total:	
Mossuro 18 SE	CUDE I OOSE & EALLEN	N EI OOP		Componen	· te			Inspected
INS	CURE LOOSE & FALLEN SULATION (80-100 SQ FT			Componen				Inspected
INS Comment	SULATION (80-100 SQ FT		Qty	Componen Estimated Unit Cost		Qty	Actual Unit Cost	Inspected
INS Comment		Γ)	Qty 1	Estimated	<u> </u>	Qty	Actual	
INS Comment # Material / Labor Insulation	SULATION (80-100 SQ FT Description / Comment	Units	_	Estimated	<u> </u>	Qty	Actual	
INS Comment # Material / Labor	SULATION (80-100 SQ FT Description / Comment	Units	_	Estimated	<u> </u>	Qty	Actual	
INS Comment # Material / Labor Insulation	SULATION (80-100 SQ FT Description / Comment	Units	_	Estimated	<u> </u>	Qty	Actual	
INS Comment # Material / Labor Insulation	SULATION (80-100 SQ FT Description / Comment	Units Each	1	Estimated	<u> </u>		Actual	

	STALL ENERGY LID TO A CESS PANEL IN HALL C			Componen	its		ı	Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Insulation	ENERGY LID	Each	1					
Other Detail						1		
			Measur	e Sub Total:			Sub Total:	
	AZE WINDOW WN-1-E	TO VERIF	Υ	Componen				Inspected
Comment 41.5" X	(38.75"; CONTRACTOR			Estimated	<u> </u>	Oftv	Actual	
Comment 41.5" X		TO VERIF <i>Units</i> Each	Qty 1	-		Qty		Inspected Total
Comment 41.5" X # Material / Labor Windows	(38.75"; CONTRACTOR Description / Comment	Units	Qty	Estimated	<u> </u>	Qty	Actual	
Comment 41.5" X	(38.75"; CONTRACTOR Description / Comment	Units	Qty	Estimated	<u> </u>	Qty	Actual	
Comment 41.5" X # Material / Labor Windows	(38.75"; CONTRACTOR Description / Comment	Units	Qty	Estimated	<u> </u>	Qty	Actual	
Comment 41.5" X # Material / Labor Windows	(38.75"; CONTRACTOR Description / Comment	Units Each	Qty 1	Estimated	<u> </u>		Actual	
Comment 41.5" X # Material / Labor Windows	(38.75"; CONTRACTOR Description / Comment	Units Each	Qty 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# Material / Labor Windows Other Detail	(38.75"; CONTRACTOR Description / Comment	Units Each	Qty 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Measure 21 GLAZE WINDOW WN-4-N			Components					Inspected		
Comment 41.5" X 3	38.75"; CONTRACTOR T	O VERIF	Y							
				Estimated	<u> </u>		Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total		
Windows	WINDOW GLAZING	Each	1							
Other Detail										
			Measur	e Sub Total:] ,	Sub Total:			
Measure 22 Insta	all/Replace Heatpump			Componen	<i>t</i> s HS1, <i>F</i>	AC1		Inspected		
			Estimated			Actual				
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total		
1 Heating Equipmen	Heatpump - 18 kBtu/h Existing, Consult Manual J Data	Each	1							
2 Labor	Heatpump - 18 kBtu/h Existing, Consult Manual J Data	Each	1							
Other Detail										
			Measure	e Sub Total:			Sub Total:			
Field Notes:										

Measure 23 DWH Pipe Insulation				Components					Inspected	
C	omment									
					Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Insulation	DHW Pipe Insulation	Each	1						
2	Labor	DHW Pipe Insulation	Each	1						
(Other Detail			1			7			
L										
			Measure Sub Total: Sub To					Sub Total:		
	Field Notes:									
			Work Order Grand Total: Grand Total:							